



**AZIMUTH GROUP
INTERNATIONAL LTD.
AZIMUTH CO.
INSPECTION DEPARTMENT**

Web: www.Azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +9647501385358
+9647504734991
Villa #194, Pank City,
Old Baharka Road,
Erbil, KRG-Iraq

CLIENT NAME	HAMAP ORG.
WORK LOCATION	SIYAN COMPANY
EQUIPMENT NAME	TLB (Backhoe)

CERTIFICATE #	AZI-23260-001
----------------------	----------------------





**AZIMUTH GROUP
INTERNATIONAL LTD.
AZIMUTH CO.
INSPECTION DEPARTMENT**

Web: www.Azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +9647501385358
+9647504734991
Villa #194, Pank City,
Old Baharka Road,
Erbil, KRG-Iraq

FITNESS CERTIFICATE

CERTIFICATE NUMBER	AZI-23260-001
CLIENT NAME	HAMAP ORG.
WORK LOACATION	SIYAN COMPANY

DATE	March 19, 2023
Ref Standrad	EN 474:2006

SUBJECT: INSPECTION OF TLB (Backhoe)

This is to certify that the under signed, a competent representative did attend to examine this equipment to ascertain the safe working condition of the equipment. At the time of examination indicated, the said equipment has no indigenous injury or sighted deformation. The equipment is safe for its intended use within the limits specified, provided there is a continuous maintenance applied and qualified operators employed.

DETAILS OF EQUIPMENTS:

DESCRIPTION	TLB (Backhoe)	MANUFACTURER	JCB
CHASSIS NUMBBER	JCB3CXAPCK2826128	SERIAL NUMBER	JCB3CXAPCK2826128
REGISTRATION NUMBER	24-22-25706	MODEL & YEAR	3 CX / 2019

OBSERVATION

The above equipment and its accessories were visually inspected and found to be Satisfactory for further use. All the safety devices and warning lights were working satisfactory. Inspection carried out and report issued with out prejudice to the rights of whomsoever it may concern for and on behalf of Azimuth Inspection Services.

DATE OF LAST EXAMINATION
--

DATE OF NEXT EXAMINATION
March 18, 2024

Examiner Name:

M.SALAH


Examiner Signature:


AZIMUTH Co.
M. Salah
Certified Inspector

Authorized name

Majid Ahmad

Authorized Signature:


INSPECTION
DEPARTMENT
AZIMUTH

THIS IS TO CERTIFY THAT the above signed competent surveyor has thoroughly and visually examined equipment in the above-mentioned place as per relevant standard. The liabilities and insurance is as per Azimuth Inspection Services.





**AZIMUTH GROUP
INTERNATIONAL LTD.
AZIMUTH CO.
INSPECTION DEPARTMENT**

Web: www.Azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +9647501385358
+9647504734991
Villa #194, Pank City,
Old Baharka Road,
Erbil, KRG-Iraq

CERTIFICATE NUMBER	AZI-23260-001	DATE OF INSPECTION	March 19, 2023
--------------------	---------------	--------------------	----------------

NO	DESCRIPTION	CONDITION	REMARKS
1	POWER UNIT	SATISFACTORY	--
2	OPERATORS CABIN	SATISFACTORY	--
3	IDENTIFICATION ON CONTROLS LEVERS	SATISFACTORY	--
4	HYDRAULIC ATTACHMENTS	SATISFACTORY	--
5	ELECTRICAL SYSTEM	SATISFACTORY	--
6	LIGHTINGS, HORNS	SATISFACTORY	--
7	HYDRAULIC SYSTEM	SATISFACTORY	--
8	WINDSHIELDS / MIRRORS	SATISFACTORY	--
9	SWING MECHANISM	N/A	--
10	BRAKES SYSTEM	SATISFACTORY	--
11	CRAWLER / TYRES / DRUM	SATISFACTORY	--
12	CONTROL LEVERS	SATISFACTORY	--
13	ROTATING WARNING LIGHT	SATISFACTORY	--
14	BUCKET CONDITION	SATISFACTORY	--
15	FIRE EXTINGUISHER	SATISFACTORY	--
16	EXHAUST SYSTEM	SATISFACTORY	--
17	SAFETY MARKINGS	SATISFACTORY	--
18	GENERAL CONDITIONS	SATISFACTORY	--

COMMENTS	NEED TO BE PROPER CLEANING ON DAILY BASIS
----------	---

Examiner Name: M. SALAH



Examiner Signature:





**AZIMUTH GROUP
INTERNATIONAL LTD.
AZIMUTH CO.
INSPECTION DEPARTMENT**

Web: www.Azimuth-iq.com
Email: info@azimuth-iq.com
Contact: +9647501385358
+9647504734991
Villa #194, Pank City,
Old Baharka Road,
Erbil, KRG-Iraq

CERTIFICATE NUMBER

AZI-23260-001

DATE OF INSPECTION

March 19, 2023



Examiner Name:

M.SALAH

M.Salah

Certified Inspector

Examiner Signature:

